	Amman and Fam D		000000000000000000000000000000000000000
	Approved For R	elease 2004/02/10 : CIA-RDP80-0	25X1A
		TION SECRET TOTAL INTELLIGENCE AGENCY	REPORT NO
		RMATION REPORT	THE OWN HOL
	1147	PRIMITION REPORT	CD NO.
COUNTRY	Poland	•	DATE DISTR. 15 Nov 51
SUBJECT	Mielec Airfield		NO. OF PAGES 2
] .	NO. OF ENCLS. 2
		 _	SUPPLEMENT TO REPORT NO.
		25X1A ´	
THE SECURET COST OF THE BAR TER, ST THE LATION OF ITS GRANDELTES BY L.	PRIVATE TRESSERVICE AFFECTION THE NATIONAL TRESSERVICE AFFECTION TO THE NATIONAL TRESSERVICE AFFECTION TO TRANSPORT AFFECTION ASSESSMENT AFFECTION ASSESSMENT AFFECTION ASSESSMENT AFFECTION ASSESSMENT AFFECTION ASSESSMENT	THIS IS L	UNEVALUATED INFORMATION

- 1. Mielec Airfield (501925N-212725E) was located about seven kilometers northeast of Mielec. It comprised an area of approximately 3000 x 3000 m and was surrounded by level terrain.
- 2. The points listed hereunder refer to an overlay of GSGS map, Poland, 1:100,000, sheet S-16, Sandomierz attached as Enclosure (A)
 - Point #1 City of Mielec (5017N-2125E)
 - #2 Main road to Sandomierz (5041N-,145E)
 - #3 Main road to Debica (5003N-2125E)
 - #4 Mielec Airfield (501925N-212725E)
- 3. The points listed hereunder refer to a memory sketch of Mielec Airfield attached as Enclosure (B):
 - Point #1 Concrete runway. This runway ran north-south and was about 1800 m long and 50 m wide. 80% was made of hexagonal concrete blocks about 100 cm wide and 30 cm thick. It had been extended about 10% at each end by ordinary concrete and was in excellent condition.
 - #2 Concrete runway. This runway ran east-west and was about 2000 m long. In all other respects it was the same as the #1 runway.
 - #3 Corrugated metal building. It was about 100 x 70 x 15 m and had a ched-type roof made of sheet-metal. The building was supported from within by a row of steel posts running down the center. I do not know the purpose of this building.

	CLASSIFICATION	SECRET	
STATE X NAVY	X	DISTRIBUTÍO	 J
ARMY X AIR E	VXCUCX	FB1X	
		•	

25X1

25X1X

(20)

- #4 Corrugated metal building. Same as building #3.
- #5 Barbed wire fence. This fence ran from the guardhouse (#8), around the field to the concrete fence (#9). The barbed wire fence was about 1.20 m high and the wires 40 50 cm apart.
- #6 Taxi ways. These were grass-covered and about 10 m wide. They connected the runways with the assembly shops (#10, #11 and #12).
- #7 Entrance from assembly shop area to airfield. The entrance was about 25 m wide and had sliding gates of sheet iron about three meters high. These gates moved on small rollers and operated automatically. They were controlled from the guardhouse (#8).
- #8 Guardhouse. This was a wooden building with a low-pitched, gable-type roof covered with tar paper. Guards stood outside the house when the gates were opened to permit aircraft to pass or to check passes when vehicles or pedestrians entered. Guards from this house also patrolled the fence of the airfield.
- #9 Reinforced concrete fence. The fence was about 2.5 m high and about 20 cm thick. It surrounded the southern, eastern and western sides of the assembly area mentioned hereunder.
- #10 Aircraft assembly building. The aircraft assembly building was about 80 x 50 x 15 m. It was constructed of reinforced concrete and had a concrete—covered arched roof about three meters high across the front of the building.
- #11. Same as Foint #40: --
- #12 Bus assembly shop. Same as Points #10 and #11.
- #13 Level agricultural area.
- #114 Main gate to assembly shop area. This gate, made of sheet metal, was about five meters wide and three meters high.
- #15 Guardhouse. This was a wooden shack about 5 x 5 x 4 m with a gable_type roof covered with tar paper.
- #16 Administration and storage building. This was a single-story, gray-plastered brick building with red tile, gable-type roof.

 I heard that this contained offices and storage rooms for spare aircraft parts.
- #17 The road to Mielec. A good, concrete road about seven meters wide which ran south-southwest to the town,

the Mielec Airfield was used primarily for the assembly and testing of PO-2 aircraft, which were assembled in the shop (#10), and taxied out on to the aircraft, which were assembled in the shop (#10), and taxied out on to the field for flight tests. I heard that 60 PO-2 aircraft were assembled in this shop. I heard that 60 PO-2 aircraft were assembled in this shop. I heard that 60 PO-2 aircraft were assembled in this shop of the parts assembled in this assembled in the immediate origin of the parts used in this assembly, but all parts, including the tires, bore Bushish assembly in from Deblin (513hN-2150E). Maintenance was performed in the shop brought in from Deblin (513hN-2150E). Maintenance was performed in the shop (#11), on civilian transport aircraft, mostly C-h?'s. This maintenance consisted of engine changes and cleaning of fuel tanks. The shop (#12) was used for the mounting of bus bodies on British Leland type chassis. There were no obstructions to interfere with take-off and landing.			
25X1X assembled in this shop. 25X1X l80 were to be assembled. 25X1X l80 were to be assembled. 25X1X used in this assembly, but all parts, including the tires, bore Busish 25X1X markings. In addition, inspections were performed in this shop on YMK-9's markings. In addition, inspections were performed in this shop on YMK-9's brought in from Deblin (5134N-2150E). Maintenance was performed in the shop brought in from Deblin (5134N-2150E). Maintenance was performed in the shop (#11), on civilian transport aircraft, mostly C-47's. This maintenance consisted of engine changes and cleaning of fuel tanks. The shop (#12) was sisted of engine changes and cleaning of fuel tanks. The shop (#12) was		sircraft, which were assembled in the shop witt,	
25X1X 180 were to be assembled.	DEVAV	field for flight tests. I heard that ou ro-2 aircrait vets	
25X1X 180 were to be assembled. The luminosite origin the limited to the luminosite origin to the parts and this assembly, but all parts, including the tires, bore Busism 25X1X used in this assembly, but all parts, including the tires, bore Busism 25X1X waskings. In addition, inspections were performed in this shop on INX-9's more performed in the shop brought in from Dellin (513kN-2150E). Maintenance was performed in the shop brought in from Dellin (513kN-2150E). Maintenance was performed in the shop (#11), on civilian transport aircraft, mostly C-47's. This maintenance consisted of engine changes and cleaning of fuel tanks. The shop (#12) was sisted of engine changes and cleaning of fuel tanks. The shop (#12) was		he airfield the shope	
used in this assembly, but all parts, including the tires, bore Busishi 25X1X used in this assembly, but all parts, including the tires, bore Busishi 25X1X markings. In addition, inspections were performed in this shop on TAK-9's brought in from Deblin (5134N-2150E). Maintenance was performed in the shop brought in from Deblin (5134N-2150E). Maintenance was performed in the shop (#11), on civilian transport aircraft, mostly C-47's. This maintenance confill, on civilian transport aircraft, mostly C-47's. The shop (#12) was sisted of engine changes and cleaning of fuel tanks. The shop (#12) was sisted of engine changes and cleaning of fuel tanks. The shop (#12) was	7 <i>5 V A V</i>	TO THE PARTY OF TH	1322232
25X1X markings. In addition, inspections were performed in this shop on YAK-9's brought in from Deblin (513hN-2150E). Maintenance was performed in the shop brought in from Deblin (513hN-2150E). Maintenance was performed in the shop (#11), on civilian transport aircraft, mostly C-h7's. This maintenance consisted of engine changes and cleaning of fuel tanks. The shop (#12) was sisted of engine changes and cleaning of fuel tanks. The shop (#12) was		180 were to be assembled.	25X1X
(#11), on civilian transport aircraft, mostly tolly so that all the shop (#12) was sisted of engine changes and cleaning of fuel tanks. The shop (#12) was the shop of the sho	25X1X		
(#11), on civilian transport aircraft, mostly tolly so that all the shop (#12) was sisted of engine changes and cleaning of fuel tanks. The shop (#12) was the shop of the sho	"	brought in from Deblin (5134N-2150E). Baintenance was performed	
		AND THE PROPERTY OF THE PROPERTY AND ALTERNATIVE AND ALTERNATI	
used for the mounting of bus bodies on writish letter type chassis. were no obstructions to interfere with take-off and landing.	. 6 44	sisted of engine changes and cleaning of the Toland time changes. There	100
were no obstructions to interfere with take-off and landing.		used for the mounting of bus bodies on aritish reland type thanks and	
	1.55	were no obstructions to interfere with take-off and landing.	

5. I heard there were 500 to 700 people employed in the assembly buildings (#10, #11 and #12) but have no further information on employment figures.

Most of these employees lived in a workers'settlement about three kilometers south of the airfield.


- end -

Enclosures: (A) Overlay of GSGS map, Sandomierz
(B) sketch of Mielec Airfield

Approved For Release 104/62/10: CIA-RDP80-00809A000600010099-8-

25X1

25)



Overlay of GSGS map, Poland laROO.000 sheet S-16, "SANDOMIERZ"

SECRET			٦
SECR	EI		_

25X1

